



Diving report for Arnarlax.

Date 12.02.18 Time : 23:05
 Location Laugardalur
 Divers Maciek
 Assistants Valdimar, Fabian

Most dive depth 39 meters

Clients rep Jónas

Following checked/worked at: Inside net cage Outside Netcage mooring to cage/moori ng plates Frame / buoys Rope to anchors / cables Other

	x					
Cage number	7					

Following factors checked while diving inside or outside of the netcage:

	Yes	No	Cause / repair
1 Was net good in sea		x	Much slack , Cage ring was broken, bottom ring had been pulled up in few places
2 Was a hole on net/abnormal tearing?		x	
3 Was dead fish collector in cage and working?		x	The liftup was in, but it had come apart and needed to be taken out.
4 Was dead fish in cage?	x		
5 Was the note overgrown/where the most?		x	
6 Something else checked/worked at?	The stone was taken from under the cage. The bottom ring was cut away from the net. And a rope attached to the liftup so it could be taken out.		

Other comments:
