



Diving report for Arnarlax.

Date 12.08.19 Time : 13:15
 Location Laugardalur
 Divers Maciek.
 Assistants Valdimar, Fabian

Most dive depth 1 meter

Clients rep Jónas

Following checked/worked at: Inside net cage Outside Netcage mooring to cage/moori ng plates Frame / buoys Rope to anchors / cables Other

	x					
Cage number	7					

Following factors checked while diving inside or outside of the netcage:

	Yes	No	Cause / repair
1 Was net good in sea			
2 Was a hole on net/abnormal tearing?			
3 Was dead fish collector in cage and working?			
4 Was dead fish in cage?			
5 Was the note overgrown/where the most?			
6 Something else checked/worked at?			Diver went into the cage to cut the feeding pipe loose from the bird net.
Other comments:			The ring on the cage had broken and the bird net was hanging loose into the cage.