

Periodic monitoring

## Diving report for Arnarlax.

Date 12.02.18 Time : 17:25

Location Hringsdalur

Divers Valdimar, Fabian.

Assistants Maciek

Most dive depth 24 meters

Clients rep Valdi

Following checked/worked at:	Inside	Outside	mooring to	Frame /	Rope to	
	net cage	Netcage	cage/moori	anchors /	Other	
			ng plates	buoys	cables	
	x					
<b>Cage number</b>	6					

Following factors checked while diving inside or outside of the netcage:

	Yes	No	Cause / repair
1 Was net good in sea		x	The net was very slack in the water because the bottom ring had been pulled up.
2 Was a hole on net/abnormal tearing?	x		Many holes were found and closed
3 Was dead fish collector in cage and working?	x		
4 Was dead fish in cage?	x		A pile of dead fish down by the basket
5 Was the net overgrown/where the most?		x	
6 Something else checked/worked at?	Net inspection, holes closed		
Other comments:	The net was very loose in the water because the bottom ring had been been pulled up to the surface, the net must have caught on to something and ripped, causing the holes.		

DATE: 12.02.18  
SITE: Hringsdalur  
TYPE  
BAG SIZE 160  
CAGE: 6  
HOLE 1:  
HOLE 2:  
HOLE 3:  
HOLE 4:

Conclusion:

x1 x2 x3 x4 x5  
x6 x7 x8 x9

All the holes were found around the surface area when the dive was performed.  
There was very much slack on the net and much movement in the water at the time when the pictures of the holes were taken.



Dead fish in the basket.



x1



x2





x3









x4




x5



x6



x7



x8



x9

